

**Work Order ID 59719**

Thursday, June 10, 2010 9:30:40 AM

Page 1

Item ID: D3752-1

Accept

Revision ID:

Item Name: Seat Frame

Start Date: 6/10/2010 Start Qty: 1.00

Required Date: 6/17/2010 Req'd Qty: 1.00

Reference: Return 2010 / RA110037

Cust Item ID:

Customer:

Approvals:

Process Plan:

Date:

Tooling:

Date:

QC:

Date: 6-10-10

SPC (Y/N):

Date:

Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

Draw Nbr

Revision Nbr

D3752

Rev C

100

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

Original B50655. Part is scrap per NCR10-057  
Identify part as scrap.

S. 6/6/10

110

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

CK 11/01/10

W 11-01-10